

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/02/2021

Submitted Date:

07/05/2021

Document Number:

699803349

**FIELD INSPECTION FORM**Loc ID 383295 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274782	WELL	PR	11/30/2009	GW	045-13392	PUCKETT 11B-25	PR

**General Comment:****COGCC Inspection Report Summary**

On Friday 7/2/21 at approximately 13:30 hours, I, Inspector Corey De Paolo,  
Conducted an on-site inspection at CAERUS PICEANCE LLC PUCKETT-66S97W /25NWNW,  
Location #383295 in Garfield County Colorado.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- 1) Unused battery next to separator with a corrective action date of 8/2/21.
- 2) Flow line heating insulation open ended and not capped with a corrective action date of 8/2/21.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the  
Compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Unused battery next to separator.		
Corrective Action:	The storage of equipment not necessary for use on location is prohibited.	Date:	08/02/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Barbed wire fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

**Equipment:**

Type: Other	# 1		corrective date
Comment:	Flow line heating insulation open ended and not capped.		
Corrective Action:	Operators will prevent and minimize adverse impacts to wildlife resources.	Date:	08/02/2021

Type: Plunger Lift	# 1	
Comment:	Well on free flow	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:	All meter runs have been calibrated in the last year.	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Centralized containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	274782	Type:	WELL	API Number:	045-13392	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		Producing							
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Compaction				
		Ditches				
Berms						
Ditches						
		Berms				
Sediment Traps						
		Gravel				
Gravel						
		Sediment Traps				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Refer to Housekeeping and Equipment for corrective actions.</a>	depaoloc	07/02/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402737721	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5470849">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5470849</a>
699803350	Photos for Insp. #699803349	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5470848">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5470848</a>