

Inspection Photos

7/12/2021

Operator: LARAMIE ENERGY LLC #10433

Location ID: 452807

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 1: Photo taken from the south end of the Location, facing west. Photos 1-3 provide an overview of the Location from west, northwest, to northeast. Photos show interim reclamation of areas not needed for production on the Location has not been performed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 4: Photo taken from the west end of the Location, facing north. Photo shows control measures to protect and stabilize the fill slopes of the Location have not been installed. Slopes predominantly loose material.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 5: Photo shows control measures to protect and stabilize the fill slopes of the Location have not been installed. Slopes predominantly loose material; erosion degradation evident.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 6: Photo taken from the east end of the Location, facing south. Photo shows control measures to protect and stabilize the fill slopes of the Location have not been installed. Slopes predominantly loose material



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 7: Photo taken from the southeast end of the Location, facing southwest. Photos 7-9 provide an overview of the Location from southwest, west to north. Photos show interim reclamation of areas not needed for production on the Location has not been performed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



July 12, 2021
39.55784891N 108.20479482W

Photo 8: See comments under photo 7.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



July 12, 2021
39.5578481N 108.20479043W

Photo 9: See comments under photo 7.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



July 12, 2021

Photo 10: Photo taken from the west end of the Location, facing northeast. Photo shows control measures to protect and stabilize the fill slopes of the Location have not been installed. Slopes predominantly loose material

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 11: Photo taken from the west end of the Location, facing northeast. Photo shows example of noxious weeds (Musk thistle) observed on the location.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 12: Photo taken from the west end of the Location, facing southeast. Photo shows example of noxious weeds (Musk thistle) observed on the location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 13: Photo taken from the west end of the pad, facing northwest. Photo shows example of noxious weeds (Musk thistle) observed on the location.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 14: Photo taken from the west end of the Location, facing northwest. Photo shows example of noxious weeds (Houndstongue) observed on the location.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 15: Photo taken from the access road. Previous inspections required Operator to conduct additional reclamation on the access road, and to implement control measures to stabilize the seeded soil and slopes. Operator submitted Resolution #402720079 showing additional seeding was performed along the slopes of the road and hydromulch applied. Photo shows hydromulch has not been maintained, and is no longer in proper functioning condition.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 16: Photo shows noxious weeds (Musk thistle) established along the access road.