

Location

Overall Good:

Signs/Marker:

Type WELLHEAD

Comment:

Corrective Action:

Date:

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: Stained soil next to Lundvall 1 well needs to be removed. See attached photo.

Corrective Action: "Properly dispose of oily waste in accordance with 905.e."

Date: 08/18/2021

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: Chainlink

Corrective Action:

Date:

Equipment:

corrective date

Type: Plunger Lift # 3

Comment:

Corrective Action:

Date:

Type: Other #

Comment: Lundvall 1 Master valve appears to be leaking. Fix or replace valve. See attached photo.

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 08/18/2021

Type: Bradenhead # 3

Comment: Appear to be plumbed to surface

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 242709 Type: WELL API Number: 123-10500 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/02/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 277446 Type: WELL API Number: 123-22962 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/02/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 277551 Type: WELL API Number: 123-22966 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/02/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 7/7/21 at approximately 0813hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Lundvall 65N66W18NESW of PDC Energy, at Location ID # 332893 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Stained soil next to Lundvall 1 well needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 8/18/21 Lundvall 1 Master valve appears to be leaking. Fix or replace valve. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 8/18/21 See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	07/07/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402739569	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5472172
699103997	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5472170