

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/30/2021

Submitted Date:

07/07/2021

Document Number:

701101684**FIELD INSPECTION FORM**Loc ID 312621 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|---------------------------------------|---------------------------------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| Byers, Jim | | jbyers@blm.gov | |
| COGCC, Laramie | 970-248-0497 | cogccnotifications@laramie-energy.com | All inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 222049 | WELL | PR | 02/01/2021 | GW | 077-08651 | HORSESHOE CANYON 2-17 | PR |

General Comment:

COGCC Follow Up Inspection Report Summary

Follow up to 12/21/2020 inspection # 699802292

Corrected action item(s)

- The braidenhead has been plumbed to surface FIRR doc# 402571092

During this inspection the following compliance issues were observed:

- No battery sign at tank battery.
- Capacity on tank has no unit of measurement. (bbl)

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|--|-------|------------|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Capacity on tank has no unit of measurement. (bbl) | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | No battery sign at tank battery. | | |
| Corrective Action: | Install sign to comply with Rule 605.e. | Date: | 10/08/2021 |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|-----|-------|--|
| Comment: | 911 | | |
| Corrective Action: | | Date: | |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------------------------|--|-------|-----------------|
| Type: Bradenhead | # 1 | | corrective date |
| Comment: | The braidenhead has been plumbed to surface. FIRR doc# 402571092 | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|-----------|-----------|---------|--------|
| PRODUCED WATER | 1 | <100 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 95 bbl | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | |
|----------------------|----------------|-----------------------|------------|
| Facility ID: 222049 | Type: WELL | API Number: 077-08651 | Status: PR |
| Insp. Status: PR | | | |
| Producing Well | | | |
| Comment: | Producing well | | |
| Corrective Action: | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Ditches | | | | |
| Check Dams | | | | | | |
| Gravel | | | | | | |
| | | Culverts | | | | |
| | | Compaction | | | | |
| Compaction | | | | | | |
| Ditches | | | | | | |
| Seeding | | | | | | |
| | | Gravel | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 402741154 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5473411 |
| 701101713 | Inspection 701101684 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5473408 |