

Inspection Photos
Operator: Simcoe
API: 067-07487
Date: 7/13/2021



Photo 1. View the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing in portions with western wheatgrass, crested wheatgrass, and rubber rabbitbrush. Other portions remain sparse and weedy and need to be monitored.



Photo 3. View the southern project area from the southwestern corner facing eastward.



Photo 4. View of drainage along access road at culvert inlet. BMP needs maintenance and does not appear to be an adequate BMP here.



Photos 5/6. View of debris within the southern and southwestern project area.



Photo 7. View the reference area comprised of pinyon and juniper woodland with sagebrush, Indian ricegrass, squirreltail, and threadleaf sunflower.