

Inspection Photos  
Operator: Simcoe  
API: 067-07486  
Date: 7/13/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing southward. Revegetation is progressing in portions with Indian ricegrass, rubber rabbitbrush, and crested wheatgrass. Other portions remain sparse and weedy and need to be monitored.





Photo 3. View the southern project area from the southwestern corner facing eastward.




Photo 4. View of Russian thistle debris within the project area.





Photo 5. View the reference area comprised of pinyon and juniper woodland with understory of prickly pear, squirreltail, sagebrush, and gambel oak.