

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/06/2021

Submitted Date:

07/15/2021

Document Number:

689806002**FIELD INSPECTION FORM**Loc ID 316782 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10469Name of Operator: ENERGY INVESTMENTS INCAddress: PO BOX 17630City: GOLDEN State: CO Zip: 80402**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone        | Email                      | Comment |
|--------------|--------------|----------------------------|---------|
| Miller, Ann  | 303-912-2188 | ann@energy-investments.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name           | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------|
| 273763      | WELL | PR     | 02/27/2005  | OW         | 107-06222 | WOLF MOUNTAIN 15-2-7-87 | PR          |

**General Comment:**

Routine FIU inspection.

Compliance issues observed:

stained soil on location

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: 303-531-5817

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | OTHER   |       |            |
| Comment:           | Stained soil at wellhead with fresh gravel on top of it.                          |       |            |
| Corrective Action: | Comply with Rule 606.<br>Properly dispose of oily waste in accordance with 905.e. | Date: | 07/30/2021 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                               |     |       |                 |
|-------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>             |     |       | corrective date |
| Type: Emission Control Device | # 1 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Pump Jack               | # 1 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Bradenhead              | # 1 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Bird Protectors         | #   |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |

**Tanks and Berms:**

|                    |   |          |           |         |        |       |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |       |
| CRUDE OIL          | 1 | 300 BBLs | STEEL AST |         | ,      |       |
| Comment:           |   |          |           |         |        |       |
| Corrective Action: |   |          |           |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Concrete           | Adequate |                     |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          | Date:               |                     |             |

|                    |   |          |           |         |        |  |
|--------------------|---|----------|-----------|---------|--------|--|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |  |
| CRUDE OIL          | 2 | 200 BBLs | STEEL AST |         | ,      |  |
| Comment:           |   |          |           |         |        |  |
| Corrective Action: |   | Date:    |           |         |        |  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Concrete           | Adequate |                     |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          | Date:               |                     |             |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

|                             |                   |                              |                   |                         |
|-----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| <b>Inspected Facilities</b> |                   |                              |                   |                         |
| Facility ID: <u>273763</u>  | Type: <u>WELL</u> | API Number: <u>107-06222</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| <b>Producing Well</b>       |                   |                              |                   |                         |
| Comment:                    |                   |                              |                   |                         |
| Corrective Action:          |                   |                              |                   | Date: <div></div>       |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 |                         |                       |               |                          |         |
| Berms            |                 |                         |                       |               |                          |         |
| Compaction       |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 689806003    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5479949">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5479949</a> |