

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/12/2021

Submitted Date:

07/12/2021

Document Number:

699803387**FIELD INSPECTION FORM**Loc ID 324312 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278163	WELL	PR	06/27/2006	GW	045-10842	PUCKETT 264-1	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 7/12/21 at approximately 13:30 hours, I, Inspector Corey De Paolo,
Conducted an on-site inspection at CAERUS PICEANCE LLC PUCKETT-67S97W /1SWNE,
Location #324312 in Garfield County Colorado.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1) Flow line heating insulation open ended and not capped with a corrective action date of 7/26/21.

- The Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the
Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Barbed wire fence		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	Flow line heating insulation open ended and not capped.		
Corrective Action:	Operators will prevent and minimize adverse impacts to wildlife resources.		Date: 07/26/2021
Type: Gas Meter Run	# 1		
Comment:	All meter runs have been calibrated in the last year.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		

Comment:		Date:	
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:		Date:	
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on free flow		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Inspector Name: De Paolo, Corey

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	Centralized containment				
Corrective Action:				Date:	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	278163	Type:	WELL	API Number:	045-10842	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Sediment Traps				
Ditches						
Berms						
Gravel						By equipment
		Gravel				
		Check Dams				
		Ditches				
Compaction						
Sediment Traps						
		Berms				

Comment: Location appears to have some gravel throughout with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Equipment for corrective actions.	depaoloc	07/12/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402745719	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5477478
699803388	Photos for Insp. #699803387	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5477472