

Inspection Photos

API: 071-06128

Operator: OGRIS OPERATING LLC

Inspection Date: 7/7/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06128 | Date: 7/7/2021

Inspection Photos



Photo 1. There is vehicle rutting along the main road. Areas of rutting need to be stabilized. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 7/7/2021

Inspection Photos



Photo 2. There is vehicle rutting along the main road. Areas of rutting need to be stabilized. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 7/7/2021

Inspection Photos



Photo 3. It appears sediment was removed from culvert inlet but has partially filled back in with recent storm events. Ongoing maintenance needs to be performed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06128 | Date: 7/7/2021

Inspection Photos



Photo 4. The same culvert outlet was excavated with sediment piles. The sediment piles need to be removed or stabilized and proper drainage is needed at the outlet along with installation of outlet protection or sediment trap.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06128 | Date: 7/7/2021

Inspection Photos



Photo 5. Further along the access road toward the location, another culvert is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 7/7/2021

Inspection Photos



Photo 6. Facing north as the road ascends the hill side. Sediment is being deposited in the area shown at red arrow. BMP's are needed along the steep grade of the road to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 7/7/2021

Inspection Photos



Photo 7. Facing back down the steep grade of the road. BMP's are needed along the steep grade of the road to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 7/7/2021

Inspection Photos



Photo 8. There is pieces of blue pipe laying on the road. This debris needs to be disposed. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 7/7/2021

Inspection Photos



Photo 9. The vehicle rutting has not been repaired since previous inspection. Areas of the road are not stabilized and susceptible to further erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 7/7/2021

Inspection Photos



Photo 10. Stormwater directed from the road has caused a washout at area shown at red arrows. Lat/Long:37.09432,-104.94607. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos



Photo 11. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 7/7/2021