

# Inspection Photos

API: 071-06340

Operator: OGRIS OPERATING LLC

Inspection Date: 7/7/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06340 | Date: 7/7/2021

## Inspection Photos



**Photo 1.** Facing north near the stream crossing. This area was observed previously with water flowing across the road. BMP's need to be installed to prevent erosion of this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06340 | Date: 7/7/2021



## Inspection Photos



**Photo 2.** Stormwater is not directed toward the culvert (at red arrow) causing stormwater to accumulate on the road. Areas of rutting need to be stabilized. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06340 | Date: 7/7/2021

## Inspection Photos



**Photo 3.** There is vehicle rutting along the main road. Areas of rutting need to be stabilized. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06340 | Date: 7/7/2021



## Inspection Photos



**Photo 4.** Stormwater is causing erosion along the side of the rip/rap.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06340 | Date: 7/7/2021



## Inspection Photos



**Photo 5.** Facing toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06340 | Date: 7/7/2021