

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/07/2021

Submitted Date:

07/19/2021

Document Number:

690201811

**FIELD INSPECTION FORM**Loc ID 307280 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		efitzgerald@ogrisop.com	
ATWATER BONNIE		batwater@ogrisop.com	
Arthur, Denise		denise.arthur@state.co.us	
		rmack@ogrisop.com	
		timothy.thomsen@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217354	WELL	PR	01/01/1995	GW	071-06130	APACHE CANYON 14-1	RI

**General Comment:**

This is a follow up of the previous stormwater management inspection #690201263, 690201547.  
The corrective action of the previous inspections have not been performed.  
Non-compliance with the Rules will be considered for enforcement.  
See attached photos and additional details within this report.

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Fail			
		Culverts	Fail			

Comment: There is vehicle rutting along the main road. There are areas of the road that are not stabilized and stormwater is not properly diverted. Repairing the road only by grading is not sufficient. Areas of erosion along the access road must be repaired and properly stabilized. This issue has been previously observed and needs to be prevented. BMP's must be implemented in accordance with good engineering practice and must be maintained. Previous corrective action has not been completed.

Corrective Action: **Install or repair required BMPs per Rule 1002.f.(2)C**

Date: 04/30/2021

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Change of Operator is listed as OGRIS OPERATING LLC.	CostaR	07/19/2021
Further stormwater erosion will occur with seasonal high intensity storm events if BMP's are not properly monitored and maintained. BMP's must be installed and maintained for all seasonal storm events to prevent erosion.	CostaR	07/20/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690201812	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5483627">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5483627</a>