

Inspection Photos

API: 125-06293

Operator: PUCKETT-WARREN OIL CO

Inspection Date: 7/13/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 125-06293 | Date: 7/13/2021

Inspection Photos



Photo 1. Facing north at the location. An abandoned pipe riser remains and the area around the riser has not established a desirable perennial vegetation cover.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 125-06293 | Date: 7/13/2021

Inspection Photos



Photo 2. There is a pipe riser that remains at the location. All abandoned risers should have been removed within 3 months of plugging the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06293 | Date: 7/13/2021

Inspection Photos



Photo 3. The area around the abandoned pipe riser consists of undesirable noxious vegetation of Cheat grass.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06293 | Date: 7/13/2021

Inspection Photos



Photo 4. Facing east toward the surrounding undisturbed vegetation which consists of Sand sage, Prairie sand reed, among other perennial native species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06293 | Date: 7/13/2021