

# Inspection Photos

API: 121-10095

Operator: PETRON DEVELOPMENT COMPANY

Inspection Date: 7/14/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 121-10095 | Date: 7/14/2021

## Inspection Photos



**Photo 1.** Facing south toward the location. The access road travels thru the location to an active sites. Areas out side of the road at the location were not reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-10095 | Date: 7/14/2021

## Inspection Photos



**Photo 2.** Facing south at the location which has not been reclaimed and remains bare of vegetation growth. The area shown by the yellow line next to the road is 50 ft. for reference.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-10095 | Date: 7/14/2021



## Inspection Photos



**Photo 3.** Facing back northwest toward the area of the location which has not been reclaimed. The area shown by the yellow line is approximately 200 ft.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-10095 | Date: 7/14/2021

## Inspection Photos



**Photo 4.** Facing northeast at the west side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-10095 | Date: 7/14/2021



## Inspection Photos



**Photo 5.** The soils throughout the location are compacted. The shovel could not penetrate through the soil.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-10095 | Date: 7/14/2021



## Inspection Photos



**Photo 6.** This photo indicates the crop was planted in this area shown by wheat stubble at red arrow. The crop did not establish any further at red arrow indicating soil issues impacted crop growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-10095 | Date: 7/14/2021