

**FORM
INSP**Rev
X/20

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/20/2021

Submitted Date:

07/20/2021

Document Number:

696303430

FIELD INSPECTION FORM
 Loc ID 437199 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

18 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Neighbors, Cory		cneighbors@hpres.com	
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437196	WELL	PR	12/01/2020	OW	123-39445	Anschutz State 5-61-19-6457BH2	PR
437197	WELL	PR	12/01/2020	OW	123-39446	Anschutz State 5-61-19-4956BH2	PR
437198	WELL	PR	12/01/2020	OW	123-39447	Anschutz State 5-61-19-6457CH2	PR
437200	WELL	SI	02/01/2021	OW	123-39448	Anschutz State 5-61-19-4956CH2	SI
445427	WELL	XX	10/28/2019		123-43049	Anschutz State 5-61-19-6457B2B	XX

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adeqaute		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Adeqaute		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked 1" Riser North of ECD and 4" Riser south of Separators. See photos		
Corrective Action:	Comply with Rule 606	Date:	07/23/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Generator		
Corrective Action:		Date:	

Type: Other	# 1		
Comment:	Line Heater		
Corrective Action:		Date:	
Type: Emission Control Device	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 14		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Sand Trap		
Corrective Action:		Date:	
Type: VRU	# 2		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	Appear to be plumbed to Surface		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical and Automation Equipment		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with the Crude Oil Tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	8	400 BBLS	STEEL AST		40.381590,-104.259720
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 437196	Type: WELL	API Number: 123-39445	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:				Date:
Facility ID: 437197	Type: WELL	API Number: 123-39446	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:				Date:
Facility ID: 437198	Type: WELL	API Number: 123-39447	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:				Date:
Facility ID: 437200	Type: WELL	API Number: 123-39448	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: SI				
Corrective Action:				Date: _____
Facility ID: 445427	Type: WELL	API Number: 123-43049	Status: XX	Insp. Status: XX
Idle Well				
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment:		Well Status is "XX" - Well Permit Expired on 04.05.2018 on Original 2A. New 2A #402132227 was submitted 08.12.2019 and returned to Draft for "Returned to draft - Exception Location Request must be updated to reflect new operator and document numbers since the permit expired 4/5/2018." Appears to have never be Drilled or Refiled for new 2A Permit.		
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 07/19/2021 at approximately 13:05, I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at High Point Operating, Anschutz State 5-61-19_20 SWSW PAD, Location #437199 in Weld County, Colorado.</p> <p>While there, I observed Reclamation Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Unmarked 1" Riser North of ECD and 4" Riser south of Separators. See photos. Comply with Rule 606. Corrective Action date 07.23.2021</p> <p>Well Status is "XX" - Well Permit Expired on 04.05.2018 on Original 2A. New 2A #402132227 was submitted 08.12.2019 and returned to Draft for "Returned to draft - Exception Location Request must be updated to reflect new operator and document numbers since the permit expired 4/5/2018." Appears to have never be Drilled or Refiled for new 2A Permit.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report.</p>	petrie	07/20/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696303431	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5484488