

Inspection Photos
Operator: Benson Montin Greer
API: 067-06290
Date: 7/20/2021



Photo 1. View the project area from the northwestern corner facing southeastward. Area is graded and recontoured. Germination not observed.



Photo 2. View of plugged well marker facing northward. Area is graded.



Photo 4. View of erosional rilling and sediment discharge from bare soils in the northeastern corner of the project area (facing upslope)



Photo 4. View of the northern edge of the project area facing eastward.



Photo 5. View the reference area comprised of gambel oak shrubland with pinyon and juniper trees and scattered ponderosa pine trees. Vegetation in the understory includes western wheatgrass, Indian ricegrass, Indian paintbrush, and goldenweed.