

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type STORAGE OF SUPL

Comment: [Large amount of equipment being stored on location see pics](#)

Corrective Action: [Comply with COGCC housekeeping rules](#)

Date: 02/05/2021

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type OTHER

Comment: [White angle iron fence around midstream equipment](#)

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date: _____
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date: _____
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date: _____
Type: Ancillary equipment	# 1	
Comment: automation		
Corrective Action:		Date: _____
Type: Vertical Separator	# 1	
Comment:		
Corrective Action:		Date: _____
Type: Pig Station	# 2	
Comment:		
Corrective Action:		Date: _____

Comment:

Corrective Action:

Date:

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run # 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment: [automation](#)

Corrective Action:

Date:

Type: Vertical Separator # 1

Comment:

Corrective Action:

Date:

Type: Pig Station # 2

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: animals have started to burrow into parts of berm, may need to be addressed in the future.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: shares containment with oil tank				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities

Facility ID: 201888 Type: WELL API Number: 001-07292 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/29/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 7/16/21 at approximately 1200 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- UPRR 24 PAN AM B 1 Company Name- P3 API- 05-123-07292 In Adams County Colorado. While there, I observed PR well This is a follow up inspection from document # 699501875 Corrective Actions are Delinquent During this inspection the following possible compliance issues were observed: Large amount of equipment being stored on location see pics Comply with COGCC housekeeping rules 2/5/21 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	07/16/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503023	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5487079