

Inspection Photos
Location Name: Champlin 75 Amoco K 2
Location ID: 320149



Photo #1 Tanks

Photo #2 Separator.

Inspection Photos
Location Name: Champlin 75 Amoco K 2
Location ID: 320149



Photo #3 unused equipment



Photo #4 unused equipment

Inspection Photos
Location Name: Champlin 75 Amoco K 2
Location ID: 320149



Photo #5 Well Head.