

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/09/2021

Submitted Date:

07/09/2021

Document Number:

693700834

**FIELD INSPECTION FORM**

Loc ID 446484 Inspector Name: ALLISON, RICK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, KPK		cogcc@kpk.com	<a href="#">All KPK Inspections</a>
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Axelson, John		john.axelson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446608	TANK BATTERY	AC	07/15/2016		-	GRANT	EI
465921	SPILL OR RELEASE	CL	07/02/2019		-	GRANT	EI

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>				
Type	Area	Volume		
OTHER				
Comment:	6' chain link fence onsite; fence secure at time of visit			
Corrective Action:				Date: _____

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date: _____

**Flaring:**

Type		
Comment:		
Corrective Action:		Date: _____

**Inspected Facilities**

Facility ID: 446608 Type: TANK API Number: - Status: AC Insp. Status: EI

Facility ID: 465921 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

**Environmental**

**Spill/Remediation:**

Comment: Remediation Project #12158: Two excavations remain open. Excavation appears unchanged since Inspection#693700805. Separator, ECDs and produced water vessel have been staged in southwest corner of site during excavation. Groundwater is exposed in western excavation on site. Operator has not submitted an implementation schedule per Rule 913.d.

Corrective Action: Submit a Quarterly Update on Form 27 Supplemental pursuant to Rule 913.e. Include results of any site investigation or excavation sampling conducted, results of monitoring well installation north of Godding Hollow Parkway, and an implementation schedule for completion of excavation, backfill and groundwater monitoring pursuant to Rule 913.d.

Date: 06/25/2021

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402743511	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5475621">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5475621</a>
693700841	GrantTankBatteryPhotos7-9-2021	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5475579">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5475579</a>