

Inspection Photos
Operator: Simcoe
API: 067-09077
Date: 7/23/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Revegetation is progressing with western wheatgrass, sand dropseed, and smooth brome.



Photo 3. View of weeds growing around equipment needing management.




Photo 4. View of musk thistles within the project area. Approximately 75 blooming individuals observed.



Photo 5. View the reference area comprised of ponderosa pine woodland with understory of gambel oak, serviceberry, western wheatgrass, and Oregon grape.