

Inspection Photos  
Operator: Simcoe  
API: 067-07400  
Date: 7/23/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and yellow goldenaster.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of rock BMP within the southern project area, full of sediment and needing maintenance.



Photo 5. View the reference area comprised of ponderosa pine woodland with understory of gambel oak, serviceberry, western wheatgrass, and Oregon grape.