

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Placard needs to be replaced. see pic		
Corrective Action:	Sign not posted or information inaccurate at oil and gas location	Date:	08/22/2021

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	OTHER		
Comment:	stained soil by load line on oil tank and separator, insulation needs to be cleaned up in separator house, unused automation equipment needs to be removed, weeds need to be managed see pics		
Corrective Action:	Comply with COGCC housekeeping rules	Date:	08/22/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	automation		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	BV CONCRETE		,

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	shares containment with oil tank
Corrective Action:	Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 202641 Type: WELL API Number: 001-08046 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/28/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 7/22/21 at approximately 1000 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Elaine 41-18 Company Name- P3 API- 05-001-08046 In Adams County Colorado. While there, I observed SI well Placard needs to be replaced. See pics Sign not posted or information inaccurate at oil and gas location 8/22/21 stained soil by load line on oil tank and separator, insulation needs to be cleaned up in separator house, unused automation equipment needs to be removed, weeds need to be managed see pics Comply with COGCC housekeeping rules 8/22/21 At time of inspection COGCC data shows production from 7/1/20, however this well uses plunger lift equipment. The COGCC may need to investigate how oil production was shown with plunger lift equipment with no gas production, or flaring reported. During this inspection the following possible compliance issues were observed: A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	07/22/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402757639	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5487084
699503025	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5487080