

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/23/2021

Submitted Date:

07/23/2021

Document Number:

700703039**FIELD INSPECTION FORM**

Loc ID 335540	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 14 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: <u>10447</u> Name of Operator: <u>URSA OPERATING COMPANY LLC</u> Address: <u>950 17TH STREET, SUITE 1900</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
, COGCC		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289262	WELL	PR	01/01/2021	GW	045-13707	BURCKLE A1	PR
289263	WELL	PR	07/07/2011	GW	045-13706	Burckle Federal A2	PR
289264	WELL	PR	01/01/2021	GW	045-13705	BURCKLE A3	PR
289265	WELL	XX	03/12/2018	LO	045-13704	Burckle A4	XX
289997	WELL	PR	01/01/2021	GW	045-13960	BURCKLE A7	PR
289998	WELL	DG	12/13/2012	GW	045-13959	Burckle A8	DG
291710	WELL	PR	01/01/2021	GW	045-14516	BURCKLE A11	PR
291712	WELL	PR	01/01/2021	GW	045-14515	BURCKLE A9	PR
297862	WELL	DG	10/07/2019	LO	045-16989	Burckle A5	DG
297863	WELL	DG	12/20/2012	GW	045-16990	Burckle A6	DG
298250	WELL	PR	07/02/2011	GW	045-17096	BURCKLE FED CA A10	PR
298251	WELL	PR	08/15/2011	GW	045-17097	BURCKLE FED CA A12	PR
422091	WELL	PR	07/08/2011	GW	045-20490	Burckle Federal A14	PR
422095	WELL	PR	08/15/2011	GW	045-20491	Burckle Federal A13	PR

**General Comment:**

COGCC Inspection Report Summary

On Friday 7/23/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a Follow up inspection at TEP Burkle A, at Location # 335540 in Garfield county Colorado.

While there, I observed normal production operations and roustabouts installing waddles at bottom of slope that has no stabilization. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.

The C/A (Pad stabilization) from prior three inspections documents 700701965, 700702239 and 700702707 has been completed. The C/A (Erosion at pig station) STILL has NOT been addressed. This is the forth inspection for this C/A.

During this inspection the following compliance issues were observed:

1. Erosion and sediment migration (riling) behind tank batteries from previous inspections. (C/A Date 1/6/2021

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

## Location

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Emission Control Device	# 1		
Comment:	tied into tank battery		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 12		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 10		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	6	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--

Inspected Facilities									
Facility ID:	289262	Type:	WELL	API Number:	045-13707	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	289263	Type:	WELL	API Number:	045-13706	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	289264	Type:	WELL	API Number:	045-13705	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	289265	Type:	WELL	API Number:	045-13704	Status:	XX	Insp. Status:	XX
Facility ID:	289997	Type:	WELL	API Number:	045-13960	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	289998	Type:	WELL	API Number:	045-13959	Status:	DG	Insp. Status:	DG
Facility ID:	291710	Type:	WELL	API Number:	045-14516	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291712	Type:	WELL	API Number:	045-14515	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	297862	Type:	WELL	API Number:	045-16989	Status:	DG	Insp. Status:	DG
Facility ID:	297863	Type:	WELL	API Number:	045-16990	Status:	DG	Insp. Status:	DG
Facility ID:	298250	Type:	WELL	API Number:	045-17096	Status:	PR	Insp. Status:	PR

<u>Producing Well</u>			
Comment:	producing		
Corrective Action:		Date:	
Facility ID:	298251	Type:	WELL
API Number:	045-17097	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	producing		
Corrective Action:		Date:	
Facility ID:	422091	Type:	WELL
API Number:	045-20490	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	producing		
Corrective Action:		Date:	
Facility ID:	422095	Type:	WELL
API Number:	045-20491	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	producing		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Drains						
Rip Rap						
		Ditches				
		Culverts				
Sediment Traps						
Waddles						
Berms						
		Rip Rap				

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.  
 1. Erosion and sediment migration (riling) behind tank batteries from previous inspections.  
 (C/A Date 1/6/2021)

Corrective Action: **Install or repair required BMPs**

Date: 01/06/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402758512	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5487860">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5487860</a>
700703044	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5487856">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5487856</a>