

Inspection Photos

API: 071-06124

Operator: OGRIS OPERATING LLC

Inspection Date: 7/29/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06124 | Date: 7/29/2021

Inspection Photos



Photo 1. Facing south along the main road. Stormwater is accumulating on the road causing widening of the road. Stormwater needs to be diverted off the road. This area shown in previous inspection was not repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06124 | Date: 7/29/2021

Inspection Photos



Photo 2. Vehicle rutting along the road has not been repaired and stormwater is causing erosion of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06124 | Date: 7/29/2021

Inspection Photos



Photo 3. Facing southwest along the main road near the location. Vehicles have caused widening of the road. This area has not been repaired since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06124 | Date: 7/29/2021

Inspection Photos



Photo 4. There is still oil inside the engine skid that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06124 | Date: 7/29/2021