

Inspection Photos

7/29/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 335904

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335904



Photo 1: Photo shows sign at the Location's entrance remains illegible, including the emergency number.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335904



July 29, 2021
39.66085021N 108.13451905W

Photo 2: Photo of the wells on site; conductors have been set. Photo shows that ongoing/continuous drilling or subsequent operations has not been performed.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335904



Photo 3: Photo taken on the North end of the Location. Photo shows example of slopes on the Location (cut/fill, and topsoil), where BMPs remain missing or insufficient to protect/stabilize. Darker soils on right is topsoil stored above a cut slope; hydromulch on topsoil no longer in proper functioning condition.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335904



Photo 4: Photo taken from the topsoil stockpile on the west end of the Location. Photo shows control measures to protect/stabilize slopes remain missing or insufficient. Photo also shows topsoil has been utilized at the base of the fill slopes/subsoils of the Location, as a berm and sediment trap/pond to manage stormwater. See photo 5.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335904



Photo 5: Photo taken from the the west end of the Location. Photo shows control measures to protect/stabilize slopes remain missing or insufficient. Photo also shows example where topsoil has been utilized at the base of the fill slopes/subsoils of the Location, as a berm and sediment trap/pond to manage stormwater. Photo shows Topsoil has not been properly separated and protected, is being mixed with subsoil, and is at risk for loss due to stormwater discharge displacing the topsoil. A second trap/pond exists on the east end of the Location.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335904



Photo 6: Photo shows example of fill slopes on the Location; BMPs to protect/stabilize slopes remain missing or insufficient.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335904



Photo 7: Photo taken from the south end of the Location, facing southeast. Photo shows example of wattles along the perimeter that have not been installed in accordance with good engineering practices, or maintained in proper functioning condition. Photo also shows example of fill slopes where BMPs to protect/stabilize slopes remain missing or insufficient.