

Inspection Photos
Operator: Logos
API: 067-05515
Date: 7/29/2015



Photo 1. View of the location from the southwestern corner facing center. Flood event has washed well pad material off of well pad and deposited down-slope and likely downstream. Water flow is from right to left here.



Photo 2. View of well and facilities. Flood water have washed away material, exposing gas lines and deposited wood and plant debris on project facilities.



Photo 3. Another view of equipment facing upslope. Gravel is largely washed offsite.



Photo 4. View of erosional scouring and flow pattern eroding beneath and around submerged vessel.



Photo 5. View of open tank full of liquid and bubbling, appears to be overflowing. Debris is floating in tank material and sediment deposition observed.



Photo 6. Another view of tank.



Photo 7. View of flow pattern from water flow due to compromised containment.



Photo 9. View of area with significant substrate loss exposing pipe and equipment infrastructure with large woody debris.



Photo 10. Another view of scoured surface and woody debris.



Photo 11. View of another area where materials are scoured away exposing liner. It appears that approximately 12-15 inches of material is washed away.