

Inspection Photos

API: 071-08854

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/27/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08854 | Date: 7/27/2021

Inspection Photos



Photo 1. Facing northwest along the former access road. There are culverts that remain along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08854 | Date: 7/27/2021

Inspection Photos



Photo 2. Facing northwest along the former access road. There are culverts that remain along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08854 | Date: 7/27/2021

Inspection Photos



Photo 3. Facing north toward the location which has not been recontoured.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08854 | Date: 7/27/2021

Inspection Photos



Photo 4. Facing northeast toward the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08854 | Date: 7/27/2021

Inspection Photos



Photo 5. There are rock rip/rap stormwater controls along the cut slope. This area along the cut slope has sparse vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08854 | Date: 7/27/2021

Inspection Photos



Photo 6. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08854 | Date: 7/27/2021