



Location			
<b>Lease Road:</b>			
Type	Access		
comment:	tall weeds along access road and ROW		
Corrective Action:	Comply with Rule 606	Date:	08/11/2021
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate, well information is faded but still visible will need to be replaced in the near future		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	tall weeds around location ROW		
Corrective Action:	Comply with Rule 606	Date:	08/11/2021
Type	TRASH		
Comment:	old v-belts on laying on location and at Pump Jack base		
Corrective Action:	Comply with Rule 606	Date:	08/11/2021
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	ancillary equipment has fabricated steel pipe and round stock		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	chainlink topped with barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	fabricated angle iron		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type:	Ancillary equipment	# 1	corrective date
Comment:	Electric panel, meter box and transformers		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 240872 Type: WELL API Number: 123-08660 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 11/04/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <input style="width: 90%;" type="text"/>						Date: _____
Corrective Action: <input style="width: 90%;" type="text"/>						
<b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary                      On Wednesday 7/28/2021 at approximately 1210 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: center;">Ditlev-Simonson C #1 at API #05-123-08660 in Weld County Colorado.</p> <p>While there, I observed a wellsite, PR at the time of inspection.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>606 Housekeeping: tall weeds growing along access road and down the ROW and around location ROW. CA date 8-11-2021. See photos 5 &amp; 6.</p> <p>606 Housekeeping: Trash laying on location and at pump jack base (old v-belts). See photos 7 &amp; 8. CA date 8-11-2021.</p> <p>608.e Mechanical condition: WH has a leak around polish rod. Lease operator arrived before I left the area and tightened the packing around the polish rod, I verified that the leak was stopped and no CA date is necessary .</p> <p>See attached photos &amp; video.</p> <p>Location: dry, Weather: clear.</p> <p>I spoke with Mani Silva KP Kauffman Supervisor at 1245 hrs. and told him about the leak around the polish rod and was told that he would send out the lease operator to take care of it.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	07/28/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402763230	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5491685">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5491685</a>
699304146	leak around polished rod	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5491676">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5491676</a>
699304147	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5491677">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5491677</a>