

Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #1 sign on tank battery



Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel

Photo #2 pad, looking west. The wet spot is believed to be from recent heavy rain. The excavated part of the pit is primarily in the fenced in area



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #3 area of investigation

Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #4 Area of investigation

Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #5 close up of debris inside of area of investigation.



Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #6 close up of debris inside of area of investigation.



Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #7 Area of investigation.



Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #8 7 Area of investigation

Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #9 7 Area of investigation

Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #10 South side of Area of investigation, it appears that surface water is weeping into excavation. Fluid shall be handled as E&P waste.



Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #11 close up of Photo #10, South side of Area of investigation, it appears that surface water is weeping into excavation. Fluid shall be handled as E&P waste.



Inspection Photos
081-07227
REM 19550
Spill 479587
Inspection Date: 8/4/2021
All Photos taken by Kris Neidel

Photo #12 Area of investigation.



Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel

Photo #13 Area of investigation.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources



Inspection Photos
081-07227
REM 19550
Spill 479587
Inspection Date: 8/4/2021
All Photos taken by Kris Neidel

Photo #14 Area of investigation, similar to Photo 10 and 11.



Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel

Photo #15 18 undisturbed adjacent soil, had mobile sediment that was observed in adjacent outcropping.





Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel

Photo #16 undisturbed adjacent soil, had mobile sediment that was observed in adjacent outcropping.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #17 undisturbed adjacent soil, had mobile sediment that was observed in adjacent outcropping.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #18 undisturbed adjacent soil, had mobile sediment that was observed in adjacent outcropping.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel

Photo #19 adjacent undisturbed soil



Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #20 adjacent undisturbed soil



Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #21 close up of adjacent undisturbed soil



Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel

Photo #22 close up of adjacent undisturbed soil



Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #23 close up of adjacent undisturbed soil



Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #

Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #25 close up of adjacent undisturbed soil



Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #26 adjacent undisturbed soil



Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #27 close up of adjacent undisturbed soil



Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel

Photo #28 outcropping near pad



Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #29 roll of chicken wire in area of interim reclamation to the east of pad.

Inspection Photos

081-07227

REM 19550

Spill 479587

Inspection Date: 8/4/2021

All Photos taken by Kris Neidel



Photo #30 area near pit