

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/05/2021

Submitted Date:

08/05/2021

Document Number:

690008143

FIELD INSPECTION FORMLoc ID 307124 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10379

Name of Operator: HARBURG* RUDOLPH W

Address: 1020 MAPLETON AVE

City: BOULDER State: CO Zip: 80304

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Harburg, Rudy	(303) 931-8099	rudy.harburg@gmail.com	
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216916	WELL	PR	01/01/2013	GW	069-06103	WESTWARD 2	SI

General Comment:

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at oil and gas location		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	09/06/2021

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:		
Type	WEEDS	
Comment:	Weeds at wellhead and battery	
Corrective Action:	Comply with Rule 606	Date: 08/13/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:		
Type	WELLHEAD	
Comment:		
Corrective Action:		Date:

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.372920,-105.065880
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Secondary containment is not sufficiently impervious to contain spilled or released materials.			
Corrective Action:	Install liner material to ensure spill or released materials will be maintained with containment structure.			Date: 09/06/2021

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	20 Bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared with crude oil tank.			
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
069-06103

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	YES		
Comment:	Well is not closed to atmosphere		
Corrective Action:	Close well to atmosphere as directed by Rule 434.b.(1)		Date: 07/29/2021

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 216916 Type: WELL API Number: 069-06103 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI at wellhead connection with flow line.

Corrective Action: _____

Date: _____

COGCC Comments

Comment

On Thursday, August 5, 2021 at 10:23, I, Craig Carlile conducted an on-site inspection at location number: 307124, location name: WESTWARD-65N69W25SWSE
 Operated by: HARBURG* RUDOLPH W 10379
 While there I observed: Audible leak at wellhead, lack of signage at wellhead and battery, uncontrolled weeds at wellhead and battery, unused equipment at battery (propane tank).
 Note: Last production report available in COGCC data base 12/1/2015, documents in review include NOAV actions addressing this issue.
 Additionally, a Form 6(N) has been submitted and approved with a status date of 7/19/2021, no evidence of plugging activity evident at time of inspection.
 Weather: Skies: Clear, Wind: Calm, Temp 76 Degrees F
 Corrective Action Dialogue: Corrective actions are outlined in this inspection document.
 This is a summary of the inspection report.

User

carlilec

Date

08/05/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402771406	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5498799
690008144	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5498798