

Inspection Photos

API: 071-08840

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/10/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08840 | Date: 8/10/2021

Inspection Photos



Photo 1. Facing west along the main access road. The road has been regraded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08840 | Date: 8/10/2021

Inspection Photos



Photo 2. The culvert has been cleaned out and grading was performed to direct stormwater toward the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08840 | Date: 8/10/2021

Inspection Photos



Photo 3. The erosion along the side of the road was repaired but no BMP's were installed to prevent erosion. Arrow points to a buried culvert that would help control erosion if repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08840 | Date: 8/10/2021

Inspection Photos



Photo 4. Facing back down the road. The erosion along the road was graded but no BMP's were installed on the long stretch of road to prevent erosion from reoccurring.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08840 | Date: 8/10/2021

Inspection Photos



Photo 5. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08840 | Date: 8/10/2021