

Inspection Photos

Operator: Advanced Wireless
API: 067-09751
Date: 8/6/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing here, as described in July 2021 inspection.



Photo 3. View of musk thistle rosettes remaining untreated within the interim reclamation area. Approximately 100 individuals observed.