

Inspection Photos

API: 071-09331

Operator: RED RIVER RANCH HOLDINGS LLC

Inspection Date: 8/11/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing south along the pre-existing access road. There is erosion occurring down the road. Stormwater is not being diverted off the road which will continue to cause erosion. BMP's are needed to control stormwater erosion in this area..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09331 | Date: 8/11/2021

Inspection Photos



Photo 2. Facing west toward the location. This area is not stabilized and revegetated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09331 | Date: 8/11/2021

Inspection Photos



Photo 3. Facing southwest toward the location. There is an area where vegetation has not established at the circled area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09331 | Date: 8/11/2021