

Caerus Piceance LLC
RA 1
Location # 334747



Location/lack of separator bath signage



Location/lack of separator bath signage



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
RA 1
Location # 334747



Location/lack of battery signage



location



Caerus Piceance LLC
RA 1
Location # 334747



Debris



Hole in containment



Caerus Piceance LLC
RA 1
Location # 334747



Lack of stabilization/compaction



Lack of stabilization/compaction



Caerus Piceance LLC
RA 1
Location # 334747



**Lack of stabilization/compaction/sediment
migration/failing ditch**



**Lack of stabilization/compaction/sediment
migration**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
RA 1
Location # 334747



Lack of stabilization/compaction/sediment migration



Lack of stabilization/compaction/sediment migration



Caerus Piceance LLC
RA 1
Location # 334747



Failing culvert



Lack of stabilization/compaction



Caerus Piceance LLC
RA 1
Location # 334747



Lack of stabilization/compaction



Lack of stabilization/compaction/failing ditch

