

# Final Reclamation Inspection

August 13, 2021

Operator: FOUNDATION ENERGY MANAGEMENT LLC- #10112

Facility ID: 330667

Inspection Document #: 697503146

Weld County, CO

NWSW Section 32 T8N R60W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: D.O.C. SHOWERS #32-12-10  
Location ID: 330667



**Photo 1.** Photo taken from the entrance of the well location access road, facing East. Photo illustrates Operator has performed final reclamation activities; however, the access road consists mostly of annual vegetation, not reflective of reference perennial vegetation.



Inspection Photos  
Location Name: D.O.C. SHOWERS #32-12-10  
Location ID: 330667



**Photo 2.** Photo taken from a portion of the well location access road, facing East. This photo illustrates this portion of the access road and most of the access road consists of cheatgrass.



**Photo 3.** Reference photo taken from the well location access road, facing North. Photo illustrates the reference area vegetation of blue grama and buffalo grass.

Inspection Photos  
Location Name: D.O.C. SHOWERS #32-12-10  
Location ID: 330667



**Photo 4.** Photo taken from the well location, facing North. It is difficult to illustrate with the photo but there was some establishment of desirable perennial plant species- prairie sandreed, blue gramma, sand dropseed and purple three-awn.



**Photo 5.** Photo taken from the well location, facing East. See comments under Photo 4.



Inspection Photos  
Location Name: D.O.C. SHOWERS #32-12-10  
Location ID: 330667



**Photo 6.** Photo taken from the well location, facing South. See comments under Photo 4.



**Photo 7.** Photo taken from the well location, facing West. See comments under Photo 4.

Inspection Photos  
Location Name: D.O.C. SHOWERS #32-12-10  
Location ID: 330667



**Photo 8.** Photo taken from the associated offsite tank battery, facing West. The tank battery is being addressed under a separate inspection.