

Inspection Photos

Operator: Hilcorp Energy
API: 067-07248
Date: 8/10/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing with western wheatgrass, sand dropseed, hairy goldenaster, and smooth brome.



Photo 3. View of southwestern diversion channel, where erosional down-cutting is occurring. Stabilization measures are needed here.



Photo 4. View of vegetation observed around the wellhead needs to be managed (ie: mowed).



Photo 5. View of the reference area comprised of open grass field and gambel oak woodland with smooth brome, western whatgrass, and hairy goldenaster.