

Inspection Photos

API: 071-08083

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/16/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 8/16/2021

Inspection Photos



Photo 1. Facing southeast along the main access road. This area of the road has been reconstructed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 8/16/2021

Inspection Photos



Photo 2. The damaged culverts need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 8/16/2021

Inspection Photos



Photo 3. Facing southwest along the main road. There is a culvert installed for temporary passage. An engineered size culvert will be needed along with bank and inlet/outlet protection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 8/16/2021

Inspection Photos



Photo 4. There is a produced water line that is bent over on the ground near the stream drainage which needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 8/16/2021

Inspection Photos



Photo 5. The cement culvert is completely filled in with material. The culvert installed is not sufficient as shown by the size of the previous culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 8/16/2021

Inspection Photos



Photo 6. Facing toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 8/16/2021