

Inspection Photos

Operator: Arkoma/Catamount
API: 067-08767
Date: 8/12/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing here with dense rubber rabbitbrush, smooth brome, crested wheatgrass, and western wheatgrass.



Photo 3. View of revegetation area in the southern cut-slope appears to be progressing.



Photo 4. View of dense Russian thistle weeds drying and will soon become debris, in the eastern well pad area. .



Photo 5. View of the reference area comprised pinyon and juniper woodland with understory of gambel oak, sagebrush, antelope bitterbrush, and squirreltail.