

Inspection Photos

Location Name: CAERUS PICEANCE LLC CASS-GARBER-68S96W /1NWNE

Location ID: 334129



Photo #4804 from entrance to location.



Photo #4805 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC CASS-GARBER-68S96W /1NWNE

Location ID: 334129



Photo #4052 from inspection #699803221 conducted on 6/10/21.



Photo #4806 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC CASS-GARBER-68S96W /1NWNE

Location ID: 334129



Photo #4054 from inspection #699803221 conducted on 6/10/21.



Photo #4807 No form of tracking BMP located at the entrance to location.