


Caerus Piceance LLC
I11W
Location # 334561



location




location

Caerus Piceance LLC
I11W
Location # 334561



location




Location/lack of separator bath signage/dimensions
of bath



Caerus Piceance LLC
I11W
Location # 334561



Location/lack of separator bath signage



Missing cap/bull plug



Caerus Piceance LLC
I11W
Location # 334561



Location/ lack of battery signage



Access road erosion



Caerus Piceance LLC
I11W
Location # 334561



Access road erosion



Access road erosion



Caerus Piceance LLC
I11W
Location # 334561



Access road erosion



Access road erosion

