

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/20/2021

Submitted Date:

08/23/2021

Document Number:

700703179

## FIELD INSPECTION FORM

 Loc ID 334561 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments

4 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257180	WELL	PR	01/01/2019	GW	045-07529	SCHAEFFER 11-8 (I11W)	PR
257181	WELL	PR	01/30/2001	GW	045-07530	SCHAEFFER 11-16 (I11W)	PR
257183	WELL	PR	01/30/2001	GW	045-07532	SCHAEFFER 11-9 (I11W)	PR
257184	WELL	SI	11/01/2020	GW	045-07533	SCHAEFFER 12-12 (I11W)	SI
281186	WELL	PR	04/18/2007	GW	045-11405	SHAEFFER 12-12B (I11W)	PR
281187	WELL	PR	04/21/2007	GW	045-11406	SHAEFFER 11-9C (I11W)	PR

**General Comment:****COGCC Inspection Report Summary**

On Friday 8/20/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus I11W, at Location # 334561 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Separator is lacking labels for heated baths (Glycol)
  2. Lack of battery signage
  3. Load out line on tank missing cap/bull plug
  4. Access road shows signs of erosion and lack of stabilization
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	See storm water		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Comply with rule 605.e		Date: 10/01/2021
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator is lacking labels for heated baths (Glycol)		
Corrective Action:	Provide proper labeling		Date: 10/01/2021
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Load out line on tank missing cap/bull plug		
Corrective Action:	Comply with rule 603.i.		Date: 10/01/2021
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Horizontal Heated Separator	# 4		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 6		
Comment:			
Corrective Action:			Date:

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:

**Inspected Facilities**

Facility ID: 257180 Type: WELL API Number: 045-07529 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 257181 Type: WELL API Number: 045-07530 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 257183 Type: WELL API Number: 045-07532 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 257184 Type: WELL API Number: 045-07533 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_  
 Comment: Last produced 10/1/2020  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 281186 Type: WELL API Number: 045-11405 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 281187 Type: WELL API Number: 045-11406 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Ditches				
Berms						
		Compaction	Fail			

Comment: [1. Access road shows signs of erosion and lack of stabilization see photos](#)

Corrective Action: [Install or repair required BMPs](#)

Date: 10/01/2021

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703185	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5512150">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5512150</a>