

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/19/2021

Submitted Date:

08/19/2021

Document Number:

699503103

FIELD INSPECTION FORMLoc ID 320132 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 79905

Name of Operator: SMITH OIL PROPERTIES INC

Address: PO BOX 219

City: BYERS State: CO Zip: 80103

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|--------------|----------------------|---------|
| Shelley, Vicki | 303-825-7405 | smithoilprop@aol.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 202777 | WELL | SI | 11/01/2019 | GW | 001-08182 | COAN 1 | SI |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment: Weeds unmanaged on location see pics

Corrective Action: Comply with COGCC housekeeping rules.

Date: 09/13/2020

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

Equipment:

corrective date

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: automation

Corrective Action:

Date:

Tanks and Berms:

Contents

#

Capacity

Type

Tank ID

SE GPS

CRUDE OIL

1

300 BBLS

STEEL AST

Comment:

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--|----------|---------------------|---------------------|-------------|
| Earth | | | | |
| Comment: unable to see if berm is acceptable until weed growth is addressed. | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|---------------------------|---|----------|----------|---------|--------|
| PRODUCED WATER | 1 | 100 BBLs | Open Top | | , |
| Comment: netting repaired | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|---|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: shares containment with oil tank | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 202777 Type: WELL API Number: 001-08182 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 10/19/2020

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

| Comment | User | Date |
|---|---------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On 8/19/21 at approximately 1125 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name-</p> <p>Company Name- Smith Oil Properties</p> <p>API- 05-001-08182</p> <p>In Adams County Colorado.</p> <p>While there, I observed SI well</p> <p>This is a follow up inspection from document # 700900280 Corrective Actions are Delinquent.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds unmanaged on location</p> <p>Comply with COGCC housekeeping rules. 8/14/20</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>Other corrective actions have been addressed, Unable to inspect if bull plug was installed due to weed growth. Netting on produced water tank appears to have been repaired, and dead animals removed. Signs are installed per COGCC rules, however some are not visible due to weed growth.</p> <p>This is a summary of inspection report.</p> | medinaj | 08/19/2021 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------|---|
| 699503104 | inspection pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513522 |