

Inspection Photos

Operator: Hilcorp Energy
API: 067-08036
Date: 8/17/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of perimeter wattles that are no longer functioning and have become debris. .



Photo 3. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with rubber rabbitbrush, greasewood, and crested wheatgrass.



Photo 4. View of the reference area comprised of greasewood and saltbush shrubland with James galleta, and sand dropseed.