

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/17/2021

Submitted Date:

08/19/2021

Document Number:

701003412

**FIELD INSPECTION FORM**

Loc ID 324831 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 83130  
Name of Operator: STRACHAN EXPLORATION INC  
Address: 383 INVERNESS PKWY, STE 360  
City: ENGLEWOOD State: CO Zip: 80112

**Findings:**

- 16 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Strachan, Steve	(303) 785-7006	sms@strachanexploration.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213004	WELL	PR	02/14/2007	OW	061-06365	FRAZEE 2-6	PR

**General Comment:**

[Routine Inspection](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Sticker on chemical tank		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks. Stickers are peeling off and need replaced		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Lease sign mounted to fence at tank battery		
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Wire fence around unit and wellhead		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Wire fence around meter shed and separator		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Wire fence around tank battery		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Ancillary equipment	# 4		corrective date
Comment:	Gas scrubber, day drum, cathodic generator and rectifier		
Corrective Action:			Date:

Type: Vertical Heater Treater	# 0		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:	Separator on south side of meter shed		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Arrow gas engine		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	CMI unit		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Meter run on north side of wellhead		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		38.438730,-103.059670
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	250bbbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared berms			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	200 BBLs	STEEL AST		38.438610,-103.059590
Comment:	Crude oil tank on south side of tank battery				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	

Comment:					
Corrective Action:				Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		38.438730,-103.059670

Comment:					
Corrective Action:				Date:	

**Paint**

Condition					
Other (Content)					
Other (Capacity)	210bbbs				
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No					
Comment:					
Corrective Action:				Date:	

**Flaring:**

Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 213004 Type: WELL API Number: 061-06365 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701003440	location photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5514974">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5514974</a>