

KP Kauffman - COGCC Inspection Photos
Location: Nessu Constolidation OLF Release
Spill ID # 476987 Date 8/23/2021



View of excavation observed at spill ID #476987; to the northeast.

View of capped 3" fiberglass flowline to the northeast edge of the larger excavation area.



KP Kauffman - COGCC Inspection Photos
Location: Nessu Constolidation OLF Release
Spill ID # 476987 Date 8/23/2021



View of north tie-in to an existing 3" (perceived) carbon steel line.



View of capped 3" fiberglass and 1.5" PVC abandoned flowlines adjacent to repaired 3" fiberglass line southern tie-in.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

KP Kauffman - COGCC Inspection Photos
Location: Nessu Constolidation OLF Release
Spill ID # 476987 Date 8/23/2021



View of fiberglass line that appears to have slipped off pipe support within the deeper portion of the excavation.

View of slight bowing at the southern tie-in with stub end.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

KP Kauffman - COGCC Inspection Photos
Location: Nessu Constolidation OLF Release
Spill ID # 476987 Date 8/23/2021



View of (2) improperly abandoned flowlines along the west edge of the larger excavated area. Blue arrow indicates cut end of flowline.

View north tie-in using buried Gruvlok clamped 90° elbow. Surface rust on bolts and on existing carbon steel pipe, where light loss of coating has occurred.

