

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/04/2021

Submitted Date:

08/19/2021

Document Number:

689806197**FIELD INSPECTION FORM**Loc ID 324591 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email         | Comment                         |
|--------------|-------|---------------|---------------------------------|
| Kauffman, KP |       | cogcc@kpk.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 212077      | WELL | IJ     | 12/28/1984  | DSPW       | 057-05129 | DWINELL 1     | SI          |

**General Comment:**

Routine UIC inspection. Compliance issues observed:  
[labels peeling on tanks](#)  
[annual and noxious weeds on location](#)

**Location**Overall Good: ☐**Signs/Marker:**

|                    |                          |       |  |
|--------------------|--------------------------|-------|--|
| Type               | TANK LABELS/PLACARDS     |       |  |
| Comment:           | Labels peeling on tanks. |       |  |
| Corrective Action: |                          | Date: |  |
| Type               | BATTERY                  |       |  |
| Comment:           |                          |       |  |
| Corrective Action: |                          | Date: |  |
| Type               | WELLHEAD                 |       |  |
| Comment:           |                          |       |  |
| Corrective Action: |                          | Date: |  |

**Emergency Contact Number:**

Comment: 303-825-4822

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |                                       |       |            |
|--------------------|---------------------------------------|-------|------------|
| Type               | WEEDS                                 |       |            |
| Comment:           | Annual and noxious weeds on location. |       |            |
| Corrective Action: | Comply with Rule 606.                 | Date: | 08/26/2021 |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

|                                 |     |       |                 |
|---------------------------------|-----|-------|-----------------|
| Type: Bird Protectors           | #   |       | corrective date |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |
| Type: Vertical Heated Separator | # 1 |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |
| Type: Bradenhead                | # 1 |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |

**Tanks and Berms:**

| Contents  | # | Capacity | Type      | Tank ID | SE GPS |
|-----------|---|----------|-----------|---------|--------|
| CRUDE OIL | 2 | 400 BBLS | STEEL AST |         | ,      |
| Comment:  |   |          |           |         |        |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate |                     |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

|                    |   |          |           |         |        |
|--------------------|---|----------|-----------|---------|--------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
| PRODUCED WATER     | 4 | 500 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate |                     |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

Venting:

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

Flaring:

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Inspected Facilities**Facility ID: 212077 Type: WELL API Number: 057-05129 Status: IJ Insp. Status: SI**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube: Pressure or inches of Hg 50 Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
(e.g. 30 psig or -30" Hg) Inj Zone: DK-LK

TC: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ Last MIT: 05/14/2018

Brhd: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: Routine UIC inspection. Well shut in at time of inspection. 50 psi on injection tubing.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: PUMP FEED

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            |                 |                         |                       |               |                          |         |
| Compaction       |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402786492    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5510874">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5510874</a> |
| 689806198    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5510861">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5510861</a> |