

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/10/2021

Submitted Date:

08/19/2021

Document Number:

689806207

FIELD INSPECTION FORM

 Loc ID 312878 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 3975
 Name of Operator: ARGALI EXPLORATION COMPANY
 Address: PO BOX 416
 City: RANGELY State: CO Zip: 81648
Findings:

- 7 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|------------------------------------|---------|
| General, Contact | | argaliexplorationcompany@gmail.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 222701 | WELL | SI | 01/01/2020 | GW | 081-06061 | FEDERAL 1-25 | SI |

General Comment:

Routine FIU inspection. Form 9 to transfer from Mustang to Argali approved 10/6/2020 document number 402424253.
 Compliance issues observed:
 signs not updated to current operator
 no bradenhead access apparent
 sediment migrating onto location

| Location | | | |
|--|--|--------|------------------|
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Sign not updated to current operator. | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | Date: | 09/20/2021 |
| Type | BATTERY | | |
| Comment: | No battery sign. | | |
| Corrective Action: | Install sign to comply with Rule 605.e. | Date: | 09/20/2021 |
| Emergency Contact Number: | | | |
| Comment: | No emergency contact for current operator on location. | | |
| Corrective Action: | Install sign to comply with Rule 605. | | Date: 09/20/2021 |
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | Annual weeds on location. | | |
| Corrective Action: | Comply with Rule 606. | | Date: 08/26/2021 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: <input style="width: 100%;" type="text"/> | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Equipment: | | | |
| Type: Dehydrator | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # | | |
| Comment: Bradenhead inaccessible or not visible. | | | |
| Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2) | | | Date: 08/30/2021 |
| Type: Bird Protectors | # | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 4 | | |
| Comment: | | | |

| | |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------------|---|----------|-----------|---------|--------|
| PRODUCED WATER | 2 | 200 BBLs | STEEL AST | | |

| | |
|--------------------|-------|
| Comment: | Date: |
| Corrective Action: | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | | | Adequate |

| | |
|--------------------|-------|
| Comment: | Date: |
| Corrective Action: | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 222701 Type: WELL API Number: 081-06061 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [No stormwater BMPs observed. Sediment migrating onto location.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 08/23/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402786496 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5510878 |
| 689806208 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5510866 |