

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/17/2021

Submitted Date:

08/19/2021

Document Number:

697601500

FIELD INSPECTION FORMLoc ID 336534 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------------|-------|--------------------------------|-----------------|
| , Spills&Remediations | | COGCCSpillRemediation@pdce.com | |
| , | | cogccinspection@pdce.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------------------|--------|-------------|------------|---------|---------------|-------------|
| 480367 | SPILL OR RELEASE | CL | 08/16/2021 | | - | Miller 5 | EI |

General Comment:

Environmental inspection of area of spill 480367 and site investigation and remediation project 18372.
PDC operated a tank battery at the area of the spill. Production equipment has now been removed.

Contractors and consultants at site during inspection.
No fencing around open excavation noted but acceptable as long as excavation site has personnel present

Environmental**Spill/Remediation:**

Comment: rule 913.b(5)B.i requires that Operators will fence or cover open excavations to prevent access when sites are no attended. Site was attended during inspection. Fencing materials and fence post did not appear to be present on site at time of inspection.

Corrective Action: Ensure that if/when site is not attended that adequate fencing is in place surrounding the open excavation seen in photos

Date: 08/20/2021

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 402786111 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5510396 |
| 697601501 | northeast corner of excavation | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5510394 |
| 697601502 | northwest corner of excavation | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5510395 |