

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/16/2021

Submitted Date:

08/16/2021

Document Number:

699803561

FIELD INSPECTION FORM
 Loc ID 334129 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

23 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278336	WELL	PR	10/18/2005	GW	045-10866	CASS-GARBER 1-52	PR
278493	WELL	PR	08/19/2015	GW	045-10886	CASS-GARBER 1-31A	PR
278825	WELL	PR	01/05/2011	GW	045-10947	CASS-DUNCAN 1-32A	PR
278829	WELL	PR	12/01/2020	GW	045-10943	CASS-GARBER 1-31C	PR
278830	WELL	PR	08/31/2007	GW	045-10942	CASS-NOCKS 1-41	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 8/16/21 at approximately 12:00 hours, I, Inspector Corey De Paolo, Conducted, an on-site inspection at CAERUS PICEANCE LLC CASS-GARBER-68S96W /1NWNE, Location #334129 in Garfield County Colorado.

While there, I observed normal production operations.

Refer to document #699803221 inspection conducted on 6/10/21. Pervious corrective action have not been completed.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1) Location lacks stabilization. Insufficient tracking BMP at entrance to location with a previous corrective action date of 6/25/21.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 7		
Comment:	All meter runs have been calibrated in the last year.		
Corrective Action:		Date:	
Type: Bird Protectors	# 5		

Comment:			Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment: Chemical tank			Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 7			
Comment: No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.			Date:	
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 7			
Comment:			Date:	
Corrective Action:			Date:	
Type: Plunger Lift	# 7			
Comment: All wells on plunger lift			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:			Date:		

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Separate containment				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:			Date:		

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Inspector Name: De Paolo, Corey

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: Separate containment					
Corrective Action:				Date:	
<u>Venting:</u>					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	278336	Type:	WELL	API Number:	045-10866	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	278493	Type:	WELL	API Number:	045-10886	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	278825	Type:	WELL	API Number:	045-10947	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	278829	Type:	WELL	API Number:	045-10943	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	278830	Type:	WELL	API Number:	045-10942	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms						
Ditches						
		Ditches				
				Material Handling And Spill Prevention		Chemical tank
Gravel	Fail					Gravel insufficient
		Compaction				
Sediment Traps						
		Berms				
		Sediment Traps				
Other	Fail					No form of tracking BMP at entrance to location.
		Check Dams				
Compaction	Fail					Location lacks stabilization

Comment: [Location lacks stabilization. No form of tracking BMP at entrance to location.](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations.](#)

Date: 06/25/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Storm water for corrective actions.	depaoloc	08/16/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402786935	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5511247
699803562	Photos for Insp. #699803561	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5511216