

# Inspection Photos

Operator: Hilcorp Energy  
API: 067-05707  
Date: 8/17/2021



Photo 1. View of the project area from southwestern corner facing center.



Photo 2. View of the southern project area facing eastward. Little desirable vegetation present within the interim reclamation areas. Rilling and erosional channeling is occurring across the fill slope.





Photo 3. View of erosional channel forming within the southern project area, approximately 1-1.5ft wide and deep. Hard hat in place for scale.



Photo 4. View of erosion occurring around submerged vessel. Area around the vessel is holding water and is not adequate containment.





Photo 5. Another view of damaged and eroding containment around submerged vessel.




Photo 6. View of unused riser and marker debris within the eastern project area. Rig anchor needs to be properly marked.





Photo 7. View of irrigation pipe on the well pad, needs to be removed. Additional pieces of broken pipe and other debris also observed.





Photo 8. View of the reference area comprised of irrigated grass field with foxtail barley, Baltic rush, and curly doc.