

Inspection Photos

Operator: Rim Operating
API: 067-09185
Date: 8/17/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of damaged fencing and debris within the northern project area.



Photo 3. View of the eastern project area facing southward. Dense kochia is present and needs to be managed. Revegetation is progressing, largely with smooth brome.



Photo 4. View of kochia up to 4-ft high, within the eastern project area.



Photo 5. View of the reference area (in background) is comprised of irrigated crop grasses such as smooth brome and orchard grass.